








APPENDIX B

EXISTING CONDITIONS MAP



EXISTING ROADWAY FACILITIES AND CONDITIONS: SEGMENT 1-A




EXISTING ROADWAY FACILITIES AND CONDITIONS: SEGMENT 1-B



EXISTING ROADWAY FACILITIES AND CONDITIONS: SEGMENT 1-C




EXISTING ROADWAY FACILITIES AND CONDITIONS: SEGMENT 2





Key



- Existing Sidewalks
- Existing Bicycle Facility
- Landscape Buffer
- Two Way Left Turn Lane
- 8 foot+ Shoulder
- Left Turn Lane
- Crosswalk
- Signalized Intersection
- Transit Stop



EXISTING ROADWAY FACILITIES AND CONDITIONS: SEGMENT 3





EXISTING ROADWAY FACILITIES AND CONDITIONS: SEGMENT 4



EXISTING ROADWAY FACILITIES AND CONDITIONS: SEGMENT 5

- Key
- Existing Sidewalks
 - Existing Bicycle Facility
 - Landscape Buffer
 - Two Way Left Turn Lane
 - 8 foot+ Shoulder
 - Left Turn Lane
 - Crosswalk
 - Signalized Intersection
 - Transit Stop



DATA SOURCE:
Basemapping - KGIS